



Photo 1 – General view of pier.



Photo 2 – View of viaduct from shore end.



Photo 3 – View of viaduct from pier head.



Photo 4 – View of pier head from viaduct.



Photo 5 – Typical pier head frame arrangement.



Photo 6 – Typical high-level beam delamination crack.